



| ØD [mm] | Typ | L [mm] | ØD ₁ [mm] | Ød ₁ [mm] | ØD ₂ [mm] | Ød ₂ [mm] | x [mm] |
|---------|-----|--------|----------------------|----------------------|----------------------|----------------------|--------|
| 20×20 | 100 | 103 | 41 | 20 | 41 | 20 | 46 |
| 25×20 | 102 | 101 | 41 | 20 | 46 | 25 | 47 |
| 25×25 | 100 | 103 | 46 | 25 | 46 | 25 | 47 |
| 32×25 | 102 | 106 | 55 | 35 | 46 | 25 | 50 |
| 32×32 | 100 | 111 | 55 | 35 | 55 | 32 | 50 |
| 40×32 | 102 | 124 | 68 | 40 | 55 | 32 | 62 |
| 40×40 | 100 | 135 | 68 | 40 | 68 | 40 | 62 |
| 50×32 | 102 | 196 | 80 | 50 | 55 | 32 | 84 |
| 50×40 | 102 | 159 | 83 | 50 | 71 | 40 | 84 |
| 50×50 | 100 | 181 | 80 | 50 | 80 | 50 | 84 |
| 63×50 | 102 | 212 | 99 | 63 | 83 | 50 | 86 |
| 63×63 | 100 | 166 | 95 | 63 | 95 | 63 | 86 |

| D [mm] | Typ | L [mm] | ØD ₁ [mm] | Ød ₁ [mm] | ØD ₂ [mm] | Ød ₂ [mm] |
|--------|-----|--------|----------------------|----------------------|----------------------|----------------------|
| 25 | 101 | 125 | 39 | 25 | 39 | 25 |
| 32 | 101 | 135 | 48 | 32 | 48 | 32 |
| 50 | 101 | 187 | 64 | 50 | 64 | 50 |

Rys. 3. Złączki zaciskowe równoprzelotowe i reducyjne SPRINT typu 100, 101 i 102